

STATE OF NEW HAMPSHIRE
BEFORE THE
NEW HAMPSHIRE PUBLIC UTILITIES COMMISSION
DIRECT TESTIMONY OF
WILLIAM H. SMAGULA

PUBLIC SERVICE COMPANY OF NEW HAMPSHIRE
RECONCILIATION OF ENERGY SERVICE AND STRANDED COSTS FOR 2007

1 I. **Introduction**

2 Q. Please state your name, position, employer and address.

3 A. My name is William H. Smagula. I am Director of Generation for Public Service
4 of New Hampshire (PSNH), a subsidiary of Northeast Utilities (NU). My business
5 address is 780 North Commercial Street, P.O. Box 330, Manchester, New
6 Hampshire 03105.

7 Q. Please provide a brief summary of your background.

8 A. I received a Bachelor of Science in Mechanical Engineering from the University
9 of New Hampshire and a Master of Science in Mechanical Engineering from
10 Northeastern University. I have worked for Public Service Company of New
11 Hampshire and then Northeast Utilities since 1978. I am a Registered Professional
12 Engineer in the states of New Hampshire, Connecticut and Massachusetts. My
13 duties have included Manager of Generation Training for the PSNH system,
14 Station Manager - Merrimack Station, Steam Production Manager - PSNH,
15 Director Fossil Generation - The Connecticut Light and Power Company, and
16 Director, Manage and Operate Services - Northeast Generation Services Company.
17 In June 2001, I assumed the responsibilities of Director - PSNH Generation in
18 New Hampshire.

1 Q. Have you ever testified before this Commission?

2 A. I have provided similar testimony in many previous Commission proceedings
3 regarding the operation of PSNH's fossil-fired and hydroelectric generating plants.

4 Q. Please describe your responsibilities as Director PSNH Generation.

5 A. In my present position, as Director - PSNH Generation, I am responsible for the
6 operation and maintenance of PSNH's generating stations. I have responsibility
7 for three fossil-fired, steam electric generating stations, nine hydroelectric
8 generating stations, two remote combustion turbine/diesel generator sites, and a
9 new biomass unit. Generation maintains a diversified fuel portfolio including
10 fossil, hydro and renewable biomass with a total generation capacity of
11 approximately 1150 MW.

12 Q. What is the purpose of your testimony in this proceeding?

13 A. The purpose of my testimony is to provide information on all outages that took
14 place at PSNH's fossil-fired, biomass-fired, and hydroelectric units and at FPL
15 Energy's Wyman Station, Unit No. 4 in which PSNH is a minority owner. This
16 information will be for the period January 1, 2007 through December 31, 2007. I
17 shall also provide information on unit equivalent availability achieved by PSNH's
18 fossil units, consistent with reporting provided in previous years. Again as
19 requested in SCRC Docket 06-068, availability including planned outages will be
20 calculated consistent with past submittals, as well as similar calculations without
21 the influence of planned outages.

22 **II. Generating Unit Operation**

23 Q. Please provide an overview of the performance of PSNH's generating units in
24 2007.

1 A. PSNH's generating units provided total generation in 2007 equal to 4,890,326
2 MWh. The fleet's availability was 99.25% during the 30 highest-priced days,
3 when customers' exposure to high market prices was the greatest.
4 The base load units, Merrimack Unit Nos. 1 and 2 and Schiller Unit Nos. 4, 5, and
5 6, had a base load capacity factor of 84.5%, which was 6% higher than PSNH had
6 modeled in the Default Energy Service calculations. Merrimack Station had its
7 highest annual generation in its 47-year history with a total generation of
8 3,283,470 MWh. Merrimack Unit No. 1 contributed to the station's success with a
9 97% availability factor resulting in its highest annual generation, producing
10 953,179 MWh. Merrimack Unit No.1 had no unplanned outages in 2007.
11 Merrimack Unit No. 2 had its third-highest annual generation in its 38-year
12 history, producing 2,330,291 MWh, which included two top-ten longest runs.
13 Schiller Station generated 969,969 MWh, the second highest annual generation in
14 its 50-year history, and operated its new biomass-fueled boiler for its first full
15 year. Contributing to the fleet's renewable energy production, Schiller Unit No. 5
16 generated 302,359 MWh and the PSNH hydro facilities generated 335,881 MWh.
17 Newington Station completed the year with a 95.7% equivalent availability factor
18 and modified its operation throughout the year to maximize value to customers.

19 PSNH's generation fleet operated well in 2007 with its Generation team focusing
20 on plant maintenance, operations, and long-term planning to provide benefit to
21 customers through reliable, compliant, and cost-effective operations and
22 management.

23 Q. Please provide a summary of why the PSNH generating units have continued to
24 operate exceptionally well, with high reliability and high availability?

25 A. The Generation management team continues to focus on four key items important
26 to long-term operational success: day-in and day-out operation and maintenance of
27 the units; corrective and preventative maintenance and maintenance conducted
28 during forced outages; pre-planning and execution of planned maintenance

1 outages; and the use of a long-term (5- and 10-year) maintenance and capital
2 expenditure planning process. The long-term maintenance plans prioritize
3 equipment maintenance and replacements to sustain reliable plant operations and
4 are founded on equipment history and ongoing condition assessment. The
5 generating stations maintain a long-standing preventative maintenance program
6 which allows for continuous improvement and proactive management of plant
7 equipment problems to best execute quality maintenance and operation of the
8 units.

9 The PSNH Generation group relies on an experienced management team and a
10 skilled work force utilizing best practices derived from experience within our
11 facilities as well as working with suppliers, contractors, experts and other
12 generating plant peers in the industry. The PSNH Generation budgets continue to
13 emphasize a proper balance between necessary spending in the most critical areas
14 and being sensitive to the overall cost of production to our customers through the
15 Energy Service rate, both long-term and short-term. The PSNH Generation group
16 works hard to ensure that larger maintenance projects are most effectively
17 executed and that capital investments are best applied to achieve high levels of
18 plant performance. The PSNH Generation group also gives extensive
19 consideration to current and emerging environmental rules and regulations, which
20 continue to challenge the electric utility industry, and looks for opportunities to
21 cost-effectively manage environmental impacts at each of the facilities.

22 Finally, PSNH Generation continues to integrate into the above management focus
23 consideration of recent recommendations by Liberty Consulting including the
24 areas of contractor control, on-line maintenance, replacement parts inventory, and
25 redundant equipment to shorten forced outage time. Consistent with the above,
26 PSNH Generation continues to develop initiatives in the areas of

- 27 • sharing information between stations regarding operational errors and
28 station improvements,

- 1 • creating a process that will be used to address distribution and transmission
- 2 groups' equipment and actions which impact generation, and
- 3 • root cause analysis to evaluate unplanned outages at major generating
- 4 stations.

5
6

7 **III. Unit Outages and Availabilities**

8 Q. Please provide a list of all unplanned outages that took place during the period
9 January 1, 2007 through December 31, 2007 for PSNH's fossil and hydro units as
10 well as for FPL Energy's Wyman Station Unit No. 4.

11 A. Attachment WHS-1 lists these outages. This listing is similar to the information
12 submitted in the past, as a reporting requirement for fossil and hydro unit outage
13 information resulting from discussion with the Staff in Docket No. DR 91-011.

14 Q. Is there any additional reporting with respect to outages?

15 A. Yes. PSNH provides outage reports for all unscheduled outages in excess of two
16 days at Newington Station, two days for either of the two units at Merrimack
17 Station, four days for any of the three units at Schiller Station, and four days at
18 Wyman Station Unit No. 4. These Outage Reports are included as Attachment
19 WHS-2. In 2007, Merrimack Unit No.1 completed three planned air heater wash
20 outages in excess of two days and had no forced outages. Newington Station did
21 not incur any outages at or above the four-day threshold. Finally, as recommended
22 and agreed to in Docket DE 07-057, brief summaries of a subset of hydro outages
23 caused by transmission, distribution or protective relay events are also included in
24 Attachment WHS-2.

25 Q. Please provide a chronological listing of the outages for which Outage Reports are
26 provided in the testimony.

1 A. The table below provides , in chronological order, the Outage Report number, unit
 2 affected, date and time removed from service, date and time returned to service,
 3 total outage duration, and cause of outage.

<u>Report No.</u>	<u>Unit</u>	<u>Off-line</u>		<u>On-line</u>		<u>Duration</u>	<u>Cause</u>
		<u>Time</u>	<u>Date</u>	<u>Time</u>	<u>Date</u>		
OR-2007-1	Schiller 5	0442	01/02	0830	01/13	11.15 days	Boiler – vortex finder failure
OR-2007-2	Merrimack 2	0740	02/09	0004	02/13	3.68 days	Superheater tube leak
OR-2007-3	Schiller 5	1640	02/09	1250	02/16	6.84 days	Boiler – bed agglomeration
OR-2007-4	Merrimack 1	1621	03/22	0518	03/26	3.54 days	Planned maintenance
OR-2007-5	Schiller 4	1014	03/26	1904	03/30	4.36 days	Superheater tube leak
OR-2007-6	Schiller 6	1410	04/29	0130	05/07	7.47 days	Generation tube leak
OR-2007-7	Merrimack 2	1707	05/29	1922	06/01	3.09 days	Economizer tube leak
OR-2007-8	Merrimack 1	1723	06/22	0334	06/25	2.42 days	Planned maintenance
OR-2007-9	Schiller 5	2117	06/22	1335	06/29	6.67 days	Planned maintenance
OR-2007-10	Schiller 5	1251	09/03	1015	09/08	4.89 days	Boiler – bed agglomeration
OR-2007-11	Merrimack 1	1619	09/20	0144	09/24	3.39 days	Planned maintenance
OR-2007-12	Merrimack 2	1620	09/24	2153	10/04	10.23 days	Planned maintenance/ feedwater flow nozzle failure

4 Q. Please provide a brief summary of each of the Outage Reports discussed above.

5 A. A summary of the Outage Reports follows:

6 OR-2007-01

7 This Schiller Unit No. 5 outage was 11.15 days in duration and began on January

8 2. The unit came off-line when the average temperature of the furnace bed

9 material was sufficiently low to trip the master fuel switch. A boiler inspection

10 found that the vortex finders in Cyclones 1 and 5 had broken at the welded support

11 flanges and fallen to the conical section of the cyclones. This internal element

12 dislodgement, combined with ash accumulation and pluggage, caused an initial

13 increase in furnace temperature that led to a loss of furnace bed fluidization. This,

14 in turn, caused the furnace to cool and the bed sand to form into lumps

15 (agglomeration), causing additional lack of combustion uniformity and resulting in

1 furnace cooling until the low temperature trip set point for the furnace was
2 reached. The welds attaching the vortex finders to Cyclones 2, 3, 4, and 6 were
3 also degraded. All vortex finders were removed and the ring flanges on all six
4 cyclones were removed. The ring flange material was either repaired or replaced.
5 All weld areas were inspected and either repaired or totally ground out and
6 rewelded. The vortex finders were reinstalled in the cyclones. Other corrective
7 and preventive work activities were completed and the unit was returned to service
8 on January 13.

9

10 OR-2007-02

11 This Merrimack Unit No. 2 outage was 3.68 days in duration and started on
12 February 9. The unit was removed from service due to a secondary superheater
13 tube leak. The leak was found on an exterior tube in the secondary superheater
14 inlet pendant. The failed tube was bent and severed. Adjacent tubes were
15 damaged by the failed tube and also had to be repaired. The repairs required the
16 erection of staging and scaffolding for safe access. A total of 64 feet of tube,
17 including two new lower bends and six welds, were removed and replaced. The
18 unit was returned to service on February 13.

19 The cause of the initial tube failure was coal ash corrosion. Because there had
20 been other secondary superheater tube failures in recent years caused by coal ash
21 corrosion, Merrimack Station management had completed targeted inspections and
22 testing during the 2006 and 2007 overhauls and scheduled replacement of this area
23 of the boiler for the spring 2008 planned overhaul.

24

25 OR-2007-03

26 This Schiller Unit No. 5 outage was 6.84 days in duration and began on February
27 9. The unit came off-line due to low furnace temperature resulting in a master fuel
28 trip. The unit had experienced erratic furnace bed temperatures over the prior few
29 days. It is suspected that a loss of wood feed condition on February 4 on one side

1 of the furnace resulted in low furnace temperatures, causing a crust to develop on
2 the bed. This period of low furnace temperature led to a master fuel trip. Because
3 residual heat of the boiler was sufficient to supply steam to the generator for a
4 period of time, the unit was initially kept on-line. After attempts to break up the
5 crust were unsuccessful, however, station management decided to take the unit
6 off-line to avoid potential damage to the unit.

7 Low furnace temperatures had allowed the bed material to agglomerate, requiring
8 a number of days to remove bed material from the boiler. The boiler inspection
9 found that two of the six cyclones were plugged with ash and required vacuuming.
10 Once the bed sand was replaced and the cyclone vacuuming and repairs were
11 completed, the unit began its start-up activities. During the process, a cyclone
12 plugged which required the bed material to be removed again. The plugged
13 cyclone was cleared and the other five cyclones were inspected and found to be
14 clear. Bed material was replaced and the unit returned to service on February 16.

15 OR-2007-04

16 Merrimack Unit No. 1 was taken off-line on March 22 for preventative
17 maintenance after 107 days of continuous operation that spanned the entire winter
18 period. This outage lasted 3.54 days. There were multiple factors for removing
19 the unit from service at this time. First, it was a relatively low-demand period. In
20 addition, a large number of maintenance items that required a shutdown for
21 completion had been identified during the long run. Completion of this work
22 would increase confidence in the ability of Unit 1 to operate through Unit 2's
23 annual overhaul in April. During the outage, numerous preventative and
24 corrective maintenance items were completed including water washing of the 1A
25 and 1B air heaters, which is required every 3 to 4 months of operation. The unit
26 was returned to service on March 26.

27 OR-2007-05

1 This Schiller Unit No. 4 outage was 4.36 days in duration and began on March 26.
2 The unit was taken off-line due to excessive water usage resulting from a
3 superheater tube leak. The boiler was filled to detect the leak, which was located
4 in the first pendant of the superheater. The cause of the leak was coal ash
5 corrosion. The repair was made with a pad weld. To identify any additional leaks,
6 a hydro test of the boiler was completed following the repair. Another small leak
7 was found in the superheater section on an existing pad weld. A pad weld repair
8 was completed and the boiler was refilled to check for any additional leaks. A
9 small leak was identified at a lower level in the furnace area. After this leak was
10 pad welded, a final hydro test was completed and the plant was brought on-line on
11 March 30.

12 OR-2007-06

13 This Schiller Unit No. 6 outage was 7.47 days in duration and began on April 29.
14 The unit was taken off-line due to excessive water usage resulting from tube leaks
15 in the steam drum area. An inspection was completed. Wet refractory at the
16 bottom of the steam drum indicated that some of the joints between the generation
17 tubes and the steam drum penetrations were leaking. Boilermakers re-rolled 24
18 tubes. A hydro test was initiated to locate any additional leaks. A small leak was
19 discovered in a generation tube weld. Operators stopped the hydro test and
20 drained the boiler below the level of the leak. The tube was repaired and the hydro
21 test was continued. This hydro test indicated new generation tube roll leaks.

22 The manufacturer of the tube rolling equipment was brought on-site to confirm
23 that the tube rolling equipment was sized and being used correctly. Once this was
24 confirmed, all 240 generation tube joints at the steam drum penetrations were
25 rolled twice and extra measurements taken to ensure that the rolls were correct. A
26 boiler hydro was completed to determine if other tube joint rolls were leaking.
27 Additional leaks were found at the screen tube and roof tube rolled joints on the

1 steam drum. These tubes were re-rolled and the hydro test was successfully
2 completed. The unit was returned to service on May 7.

3 OR-2007-07

4 This Merrimack Unit No. 2 outage was 3.09 days in duration and started on May
5 29. The unit was taken off-line due to excessive water usage resulting from an
6 economizer tube leak. The boiler inspection found three leaks in the economizer.
7 An original weld on a top tube had eroded as a result of coal ash corrosion and
8 caused subsequent damage to five other tubes below it. Three repairs were made
9 with Dutchmen and three with pad welds. The boiler pressure check was
10 successful and the unit was brought back on-line on June 1.

11 The economizer sections are original plant equipment and are 39 years old.
12 Recognizing the potential for leakage due to age and susceptibility to coal ash
13 corrosion, the station has been conducting enhanced inspection and testing of the
14 economizer during each overhaul since 2006.

15 OR-2007-08

16 Merrimack Unit No. 1 was removed from service on June 22 to conduct
17 preventative maintenance after an 89-day run. The need for an air heater wash
18 was apparent, based on pressure drop increase and time on-line. To avoid outages
19 during the high-demand summer period, ISO-NE was contacted and a weekend
20 outage planned with the unit being removed Friday evening. This maintenance
21 outage lasted 2.42 days. A considerable number of maintenance items on the
22 outage back log list were completed. Water washing of the 1A and 1B air heaters,
23 as typically required every three to four months of operation, governed the
24 outage's critical path. This maintenance outage was intended to enable the unit to
25 run successfully through the upcoming summer peak period. The unit was
26 returned to service on June 25.

1 OR-2007-09

2 This Schiller Unit No. 5 outage was 6.67 days in duration and began on June 22.
3 This maintenance outage was coordinated with ISO-NE to complete a number of
4 boiler maintenance items which had been identified over a six-to-eight-week
5 period. The new boiler had experienced periodic high cyclone temperatures as
6 well as air and fuel swings which were limiting the firing capability and often
7 causing reductions in boiler steam output. PSNH, along with the boiler
8 manufacturer, Alstom, had completed a number of on-line efforts to resolve the
9 operational constraints by modifying boiler control system logic. These
10 adjustments resulted in boiler performance improvements. However, during the
11 outage a number of additional activities were conducted to further improve
12 performance of the unit, including inspecting the primary air system, cleaning the
13 tuyeres, replacing the bed material, and cleaning and inspecting the cyclones.
14 Other corrective and maintenance activities were completed and the unit was
15 returned to service on June 29.

16 OR-2007-10

17 This Schiller Unit No. 5 outage was 4.89 days in duration and began on September
18 3. The unit was removed from service due to an agglomeration of the bed material
19 which significantly impacted boiler performance. The station had been monitoring
20 high circulating water discharge temperatures for a couple of weeks. To improve
21 the water discharge temperature, a water box cleaning was planned for September
22 2. During a water box cleaning, one half of the condenser is isolated which
23 requires steam flow and load to be reduced, which further requires operators to
24 reduce fuel input and remove bed material from the boiler. While bringing the
25 plant through this transition, operators also monitor air flow differential pressure
26 (DP) across the furnace bed in order to ensure that the appropriate bed temperature
27 for the plant condition is maintained. Cleaning one half of the water boxes at a
28 time is not uncommon at Schiller Station, but brand new when being done in

1 conjunction with operation of the new wood boiler and its significantly different
2 operational characteristics.

3 During the transition, the boiler began to experience temperature and pressure
4 swings. Though the boiler was stabilized, indications were that bed material
5 problems had developed. A number of on-line solutions to correct bed material
6 consistency were attempted. However, it was determined that the unit should be
7 brought off-line to correct the problem.

8 The boiler was inspected. The bed material had enough agglomeration to
9 necessitate removal by manually vacuuming the tuyere area. It took
10 approximately four days to replace the estimated 100 tons of bed material in the
11 furnace. A number of other inspections and repairs were performed while the unit
12 was off-line to maximize unit performance and operations. Once complete, the
13 unit was returned to service on September 8.

14 OR-2007-11

15 Merrimack Unit No. 1 was taken off-line on September 20 for 3.39 days to
16 perform preventative maintenance following an 81-day run through the summer
17 peak period. Water washing of the 1A and 1B air heaters was required and
18 dictated the critical path. A boiler inspection was completed. Work activities that
19 had accumulated on the maintenance outage back log list were completed. After
20 completion of this maintenance outage and its return to service on September 24,
21 the unit ran continuously for the remainder of the year.

22 OR-2007-12

23 This Merrimack Unit No. 2 outage was 10.2 days in duration. The unit initially
24 came off-line on September 24 for planned maintenance after operating for 113
25 consecutive days through the summer peak load period. A number of maintenance
26 activities had accumulated on the outage backlog list after an extensive run of

1 nearly 4 months. A boiler inspection was completed, a number of routine
2 inspections and cleanings were completed, and a number of other repair activities
3 were performed.

4 During startup from the maintenance outage on September 28, operators observed
5 that feedwater flow was not consistent with other plant parameters. This
6 feedwater flow information and signal is a critical operational parameter that must
7 be available for unit operation. The start-up was stopped to investigate the
8 problem. A boroscope examination revealed that the feedwater flow nozzle,
9 located inside the feedwater line, had become detached. The flow nozzle is the
10 sensing device from which the flow measurement is calculated. The repair
11 consisted of removing about 14 feet of the heavy-walled feedwater line and then
12 repairing and re-welding the nozzle to the inside of the feedwater line section. The
13 repaired nozzle, attached to the feedwater line section, then was shipped to Alden
14 Laboratories in Massachusetts for calibration. When the flow nozzle/pipe
15 assembly returned, the heavy-walled feedwater pipe section was welded back in
16 place, radiographically inspected, and stress relieved. In parallel with this repair, a
17 spare flow nozzle was ordered, and a new one was manufactured by the station's
18 machine shop as part of a contingency plan. As a result of this incident, a program
19 to inspect and replace other flow nozzles throughout the system was implemented.
20 The unit returned to service on October 4.

21 Q. Do you have any additional reporting requirements associated with this submittal?

22 A. Yes. PSNH Generation completed and submits herein an assessment of the
23 Merrimack Unit No. 1 scheduled overhaul frequency as discussed in the Liberty
24 Auditing consultant's testimony and summarized in the settlement agreement. The
25 report is included in attachment WHS-4 of this testimony.

26 Q. Does this conclude your testimony?

27 A. Yes, it does.