

NH PUBLIC UTILITIES COMMISSION
Safety Division, 21 South Fruit Street, Suite #10, Concord NH 03301-2429
REPORT OF PROBABLE VIOLATION OF UNDERGROUND UTILITY
REGULATIONS AND/OR DAMAGE TO UNDERGROUND FACILITIES

EXHIBIT
15
DG 17-070

NEGATIVE REPORT Month: Year: No probable violation of underground utility regulations or damage to underground facilities occurred since the date this company last filed a report as required by Puc 803.02.

INCIDENT DATE: (mo/day/yr) 6 15 2018 TIME: a.m. 12:20 p.m.
REPORT DATE: (mo/day/yr) 6 15 2018

LOCATION OF VIOLATION / DAMAGE: Long: Lat:
Address: 62 White House RD PUBLIC WAY ☒ RIGHT OF WAY ☐
City: Rochester
State: NH Zip Code: 03867 EASEMENT ☐ PRIVATE PROPERTY ☐

PERSON REPORTING: (FACILITY OPERATOR, EXCAVATOR OR ANY OTHER PARTY)
Name: David Apkarian Home No. AREA CODE 7 DIGIT NUMBER EXT.
Company: (if applicable) Unitil, Northern Utilities Work No. 603 436-0310
Address: 325 West Road Fax No. 603 436-9473
City: Portsmouth Cell No.
State: NH Zip Code: 03801 email address

EXCAVATOR / FACILITY OPERATOR:
Name: NEUCO Home No. AREA CODE 7 DIGIT NUMBER EXT.
Company: (if applicable) Work No. 617 389-5500
Address: 94 Glenn St Fax No.
City: Lawrence Cell No.
State: MA Zip Code: 01843 email address

DOING WORK FOR:
Name: Work No. AREA CODE 7 DIGIT NUMBER EXT.
Company: (if applicable) Unitil, Northern Utilities Cell No.

FACILITY DAMAGED: include type, size, material, pressure / voltage or Safety Concern:
 4" Bare Steel Main

ESTIMATE OF DAMAGE: Excavator Billed for Damage? YES ☐ NO ☒

PERSONAL INJURY: 0

DESCRIPTION OF INCIDENT:
 NEUCO has been excavating to replace the existing 6" steel gas main and had been removing the dead 4" bare steel main because that where the new 12" CS gas main was to be installed. A 4" stub was left alive off the 6" main and that's what was hit.

TYPE OF MARKING:

OTHER PERTINENT INFORMATION: (photos, diagrams, sketch, etc.)
 No records of the 4" stub.

Name:

| | | |
|-------------------------------------|--|--|
| <input checked="" type="checkbox"/> | 1. Notification completed, DIG-SAFE NUMBER: <input type="text"/> 20182205343 | |
| <input type="checkbox"/> | 2. Notification completed, marked, markings not maintained | |
| <input type="checkbox"/> | 3. Notification completed, location was not marked | |
| <input type="checkbox"/> | 4. Notification completed, marked, damage occurred | |
| <input type="checkbox"/> | 5. Excavating outside the pre-marked area | |
| <input type="checkbox"/> | 6. Excavation classified as EMERGENCY SITUATION | |
| <input type="checkbox"/> | 7. Excavator failed to observe 18-in. tolerance zone | |
| <input type="checkbox"/> | 8. Excavator failed to notify nonmember facility operator | |
| <input type="checkbox"/> | 9. Excavating on an expired ticket | |
| <input type="checkbox"/> | 10. Procedures for notification not followed DIG-SAFE NOT NOTIFIED | |
| <input type="checkbox"/> | 11. Failure to notify of damage | |
| <input checked="" type="checkbox"/> | 12. Pre-marked YES <input checked="" type="checkbox"/> NO <input type="checkbox"/> | |
| <input checked="" type="checkbox"/> | 13. Operator's markings were incorrect due to: | |
| | a. LOCATOR ERROR | |
| | b. INCORRECT RECORD | |
| | c. NO RECORD | |
| | 14. Facility operator failed to mark in a timely manner | |
| | 15. OTHER | |

Signature: David Apkarian Title: Supervisor

* Reviewed by signing authority listed (if submitted electronically) Yes ☒ No ☐